

Division of Oil, Gas, & Mining  
Mining Report

02/06/96

MINE ID: S0030009

MINE NAME: PARK VALLEY II

OPERATOR: BOWN, WILLIAM L./PRESTON BOWN  
CONTACT: WILLIAM BOWN  
ADDRESS: 842 WEST 400 NORTH  
WEST BOUNTIFUL UT 84087  
  
PHONE: (801)295-0601

Surface Owner: STATE  
Mineral Owner: STATE

BLM #:  
Lease #: ML 46137

Qtr-Qtr-Qtr1	Qtr-Qtr1	Qtr1	Qtr-Qtr-Qtr2	Qtr-Qtr2	Qtr2	Sec	Town	Range
		AL				2	13.0N	14.0W

Permit Status: APP

Mine Type [(S)urface, (U)nderground]: S

Mine Status: SUS

Acreage: 0

Status Date: / /

Minerals Mined  
QUARTZITE FLAGSTONE

DATE  
RECEIVED

TENTATIVE APPROVAL  
DATE

FINAL APPROVAL  
DATE

LAST INSPECTED

11/10/87

/ /

11/18/87

/ /

BOND TYPE:

BOND AMOUNT:

ANNUAL REPORT YEAR: 95

	YTD	Total				
NONCOMP NOTICES:	0	0	DATE ISSUED:	/ /	DATE RESOLVED:	/ /
VIOLATIONS:	0	0	DATE ISSUED:	/ /	DATE RESOLVED:	/ /
REVISIONS:	0	0	DATE REC'D:	/ /	DATE APPROVED:	/ /
AMENDMENTS:	0	0	DATE REC'D:	/ /	DATE APPROVED:	/ /

COMMENTS:

ROCK IS HANDPICKED FROM GROUND AND LOADED ONTO 4 X 4 TRUCK. VERY LITTLE SURFACE DISTURBANCE IS ANTICIPATED. CONTINUED GATHERING OF SURFACE QUARTZITE BUILDING STONE USING EXISTING 4X4 TRAILS. LEASE WAS DROPPED FOR NON-PAYMENT AND WILLIAM BOWN (PRESTON'S SON) PICKED UP THE LEASE. A NEW LEASE #IS ASSIGNED, BUT TRANSFER FORM WAS FILLED OUT BY BOTH FATHER & SON. 1995 REPORT STATED CANNOT OPERATE YET AS ACCESS CAN'T BE OBTAINED. APPEAL SOUGHT TO STATE ATTORNEY GENERAL. AWAITING SOLUTION.